


Camera using Scenario



2 meters




2 meters



Further Check
Required



2 meters



1) People Stand 2 meters before the camera for 3 seconds, Have their temperature checked and pass if normal (probably under 37 °C)

2) People over 37 °C temperature will give alarm and will be sent for more accurate temperature check

Entry Point



1 : 36.7 °C

3 More than 7~8 meter away




perform better
when target is
within 2~3 meter



2 : 36.8 °C


3 : 34.2 °C ← Low Accuracy : More than 7~8 meter away



1 : 36.7 °C

GIVES ALARM
IF ANY OBJECT
IN THE SCENE
HAS HIGHER
TEMPERATURE
THAN TRIGGERING
TEMPERATURE

ALARM GOES TO
NVR / ISS



2 : 39.8 °C